

MATERIAL SAFETY DATA SHEET

PAGE 1 OF 2

IDENTITY	QwikGo®
-----------------	----------------

SECTION I

MANUFACTURER: A.L. WILSON CHEMICAL CO. 1050 HARRISON AVENUE P.O. BOX 207 KEARNY, NJ 07032	EMERGENCY TELEPHONE NUMBER	800-424-9300 or 703-527-3887
	TELEPHONE NUMBER FOR INFORMATION:	201-997-3300
	DATE PREPARED:	October 1, 2003

SECTION II - IMPORTANT INGREDIENTS / IDENTITY INFORMATION

IMPORTANT COMPONENTS	CHEMICAL IDENTITY	CAS #	%	TLV
LINEAR PRIMARY ALCOHOL ETHOXYLATE	MIXTURE C ₁₂ & C ₁₅ ALCOHOL ETHOXYLATE	68131-39-5	<5%	ND
POTASSIUM HYDROXIDE	KOH	1310-58-3		2MG/M ³
WATER	H ₂ O	7732-18-5		
TRIETHANOL AMINE	(HOCH ₂ CH ₂) ₃ N	102-71-6	<3%	ND
ISOPROPYL ALCOHOL	(CH ₃) ₂ CHOH	67-63-0	<1%	STEL= 500 PPM

SECTION III - PHYSICAL / CHEMICAL CHARACTERISTICS

BOILING POINT	212° F	SPECIFIC GRAVITY (H₂O=1)	approx. 1.01
VAPOR PRESSURE (mm Hg)	ND	MELTING POINT	NA
VAPOR DENSITY (air =1)	ND	EVAPORATION RATE (butyl acetate =1)	ND
SOLUBILITY IN WATER	100%		
APPEARANCE AND ODOR	light yellow with surfactant odor		

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLASH POINT (method used) 180° F T.C.C. Water base. Will not sustain combustion.	FLAMMABLE LIMITS ND
EXTINGUISHING MEDIA water, carbon dioxide "CO ₂ ", dry chemical	
SPECIAL FIRE FIGHTING PROCEDURES NA	
UNUSUAL FIRE AND EXPLOSION HAZARDS NA	

SECTION V - REACTIVITY DATA

STABILITY stable	CONDITIONS TO AVOID
INCOMPATIBILITY (MATERIALS TO AVOID) acids	
HAZARDOUS DECOMPOSITION PRODUCTS none known	
HAZARDOUS POLYMERIZATION will not occur	

See Page 2 for more information.

SECTION VI - HEALTH HAZARD DATA**EFFECTS OF OVEREXPOSURE****EYES:** May cause irritation seen as redness.**SKIN:** May cause irritation.**INGESTION:** Coughing, burning sensation.**INHALATION:** Vapors may be irritating.**FIRST AID****EYES:** Immediately flush thoroughly with water. Get medical attention.**SKIN:** Flush thoroughly with water.**INGESTION:** See a physician as soon as possible.**INHALATION:** If affected, remove victim from exposed area.**SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE****STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED**

Flush with water. See below.

WASTE DISPOSAL METHOD

Absorb and dispose of in accordance with federal, state and local regulations.

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

Keep cool, do not store with acids..

SECTION VIII - CONTROL MEASURES**RESPIRATORY PROTECTION**

none expected to be needed

VENTILATION

adequate local exhaust

PROTECTIVE GLOVES

desirable

EYE PROTECTION

desirable

OTHER PROTECTIVE CLOTHING OR EQUIPMENT

chemical apron

WORK/HYGIENIC PRACTICES

Practice good personal hygiene.

NA = Not Applicable**ND = Not Determined**

See Page 1 for more information.